



INSTALLATION

INSTRUCTIONS

TOOLS REQUIRED

Alcohol, hair dryer or heat gun, scissors, masking tape, squeegee, heated indoor space, and adhesive remover (if glue needs to be removed).

STEP 1 - FIRST THING TO DO

- Remove the graphics from the shipping tube and lay them flat for 12 to 24 hours.
- Move the machine into a warm area of at least 20°C and allow it to acclimate before beginning the installation.

! CAUTION : The installation must be done at an ambient temperature of at least 20°C.

STEP 2 - PREPARING THE MACHINE



Carefully wash your machine with soapy water and dry it.

If there are existing stickers, remove them using a heat gun or a hair dryer. If necessary, remove any adhesive residue with a remover. Then, clean the areas where new stickers will be applied with isopropyl alcohol and allow them to air dry.

The machine must be clean, dry, and free of grease, glue, wax, or dust before beginning the Graphxdp installation.

! Do not use any type of degreaser such as Pledge, WD40, etc. These oil-based products make plastic surfaces slippery, and the graphics kit will not adhere properly and will eventually peel off. So, take the time to thoroughly wash the machine. If your dealer has applied SC1 to your snowmobile, it's important to be aware, as this product leaves a protective coating on your machine. If this is the case, you will need to clean it with Brake Cleaner or another strong product to remove this coating.

STEP 3 - INSTALLATION



To begin, study the installation map to determine where all the sticker pieces go on the machine.

If you wish, you can cut around the edges of the pieces as closely as possible while keeping the backing on the decal, and temporarily secure them in place on the machine using masking tape. This step will help you align the stickers correctly and give you an overall view before permanently adhering them.

To apply the pieces: place the piece in its position on the machine and use a long strip of masking tape to stick it down the center of the piece. Using the tape as a central hinge, pull one side of the sticker back on itself and peel off the backing paper. Cut the backing paper close to the hinge. Adhere from the center outward using your squeegee with overlapping straight strokes from top to bottom. Once half of the sticker is properly applied, remove the masking tape and repeat the steps for the other half.

STEP 4 - HEAT



Stickers adhere better with additional heat and pressure (be careful not to overheat). Use a heat gun or hair dryer to evenly warm each piece. Then, press down on each piece, paying special attention to the edges to ensure optimal adhesion. This installation step is crucial, and if not done properly, the stickers may peel off.

⚠️ *Important : Allow the stickers to adhere for 24 hours before taking the machine out in the cold.

Graphxdp is not responsible for incorrect sticker installation. We use high-quality vinyl designed for easy installation and optimal adhesion. The laminate is designed to protect the vinyl sticker effectively. However, a sticker is not indestructible, and its longevity depends on both the installation and the abrasion from various conditions encountered during machine use.